



Photo #1: 629 Luray Street—Step cracks in foundation wall. Cracks extend down along wall from 2nd floor window.



Photo #2: 619-621 Courtland Street—Step cracks from 1st floor window, and windowsills and door lintel not level.



Photo #3: 710 Roosevelt Boulevard—End of row—Step crack from roof to foundation wall.



Photo #4: 4510 Reese Street—Interior Top of front door, in living room, not level.
C-6



Photo #5: 4506-4508 Reese Street—Door lintels and front porch not level, repaired step cracks, and low point in street.



Photo #6: 4523 Reese Street—Door lintel not level, and step cracks from 1st floor window to 2nd floor.

C-7



Photo #7: 4523 Reese Street (from Fifth and Annsbury) End of row—Front and rear corner of north wall not plumb.



Photo #8: 325-327 Raymond Street at corner of Fourth Street—Party wall settlement and step cracks from 1st floor window down to foundation wall.



Photo #9: 301-327Raymond Street (rear in alley) Repaired step cracks.



Photo #10: Site of former Logan Sinking Homes that have been demolished.



Photo #11: Continuing demolition of sinking homes in Logan area.