



PHOTO #1. 6163 Vandike St.-Front of row home - Repaired step cracks from 2nd floor window.



PHOTO #2. 6144 Hegerman St.-Rear of row home-Repaired step cracks from 1st floor and 2nd floor windows.