



**PHOTO #3.** 4719 Benner St.-Side of row home-Repaired step cracks from 2<sup>nd</sup> floor windows.



**PHOTO #4.** 6355 Vandike St.-Front of row home-Repaired step cracks from 2<sup>nd</sup> floor windows.