



**PHOTO #5.** 4500 Robbins Ave.-Side of row home-Repaired step cracks from corner of wall down through foundation wall.



**PHOTO #6.** 4123 Tackawanna St.-Rear of row home-Repaired step cracks from 2<sup>nd</sup> floor window and 1<sup>st</sup> floor window.