



PHOTO #8. 6153 Vandike St.-Rear of row home—Hairline stepped settlement crack. Common wall appears to have settled.




PHOTO #9. 6131 Vandike St.-Rear of row home-Repaired step crack from 1st floor window.