



**PHOTO #10.** 6133 Vandike St.-Rear of row home-Floor slab settled. Garage door cut crooked.



**PHOTO #11.** 6148 Vandike St-Rear of row home-Repaired step cracks from 1<sup>st</sup> floor and 2<sup>nd</sup> floor windows.