



**PHOTO #12.** 6122 Vandike St.-Rear of row home-Repaired step crack from 1<sup>st</sup> floor window to top of rear door and foundation wall.



**PHOTO #13.** 6131 and 6133 Torresdale Ave.-Rear of row homes-Repaired step crack from 2<sup>nd</sup> floor windows to porch and 1<sup>st</sup> floor windows.