



PHOTO #14. 6341 Vandike St.-Rear of row homes-Repaired step crack from 1st floor window. Doors out of plumb and common wall appears to have settled.




PHOTO #15. 6100 Vandike St.-Rear of row home- Step crack from 2nd floor window to top of parapet wall. Window is not level.