



**PHOTO #16.** 4728 Levick St.—side of row home—repaired step cracks in masonry from 2<sup>nd</sup> floor windows to 1<sup>st</sup> floor windows and 2<sup>nd</sup> floor windows to top of parapet wall.