


# Appendix D

## Sewer/Lateral Investigation




10-inch sewer main downstream of 4452 Reese Street manhole.  
Cracks in sewer.



10-inch sewer main downstream of 4452 Reese Street manhole.  
Cracks in sewer.



Dip in sewer holding water at 4506-4510 Reese Street.



Broken lateral at 4510 Reese Street. Water in upper left corner.



Broken lateral at 4510 Reese Street. Cracked pipe in center.



Broken sewer main at Reese and Wingohocking Street



Broken sewer main at Reese and Wingohocking Street