



**US Army Corps
of Engineers**
Philadelphia District

Southeastern Pennsylvania Environmental
Assistance Program
(Section 566 of Water Resources Development Act of 1996)

Logan (Feltonville) Sinking Homes Study
Philadelphia, PA

Prepared By

**U.S. ARMY CORPS OF ENGINEERS
PHILADELPHIA DISTRICT**

JULY 2000

***** NOTICE *****

This document is an INFORMATIONAL REPORT issued to the client, the Philadelphia Federal Congressional Delegation, only. Use of this report by other parties for any reason is prohibited except for general informational purposes. Other usage will be considered beyond the scope of the study and will discharge the U.S. Army Corps of Engineers, Philadelphia District of any responsibility whatsoever for any such reliance on this report or occurrence of any conditions not identified in this report.

This report is limited in the scope of the study and/or investigation as contained in report, and is rendered on an “opinion” basis. Latent or concealed defects, which cannot reasonably be discovered without the use of Engineering practices beyond those contained in the Scope of Study and/or Description of Work, may not be identified.

While every reasonable effort and good engineering practices subject to the limitation of funding were used to ascertain the present condition of the inspected areas, the U.S. Army Corps of Engineers, Philadelphia District does not make any representation, guarantee, or warranty as to the reported condition or any property’s future condition.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
1.0 Executive Summary.....	1
2.0 Description/Background of Project.....	6
2.1 Study Area.....	6
2.2 Scope of Study/Investigation.....	7
3.0 Topographical Change Maps.....	9
3.1 US Army Corps of Engineers, Philadelphia District Map.....	9
3.1.1 Description of Work.....	9
4.0 Subsurface Investigation.....	10
4.1 Geologic Setting.....	10
4.2 Previous Geotechnical Investigations.....	10
4.2.1 Lippincott Engineering Associates, Inc. Study of Soil Conditions....	10
4.2.2 Lippincott Supplemental Study of Soil Conditions	11
4.3 US Army Corps of Engineers, Philadelphia District’s Geotechnical Investigation.....	11
4.3.1 Subsurface Conditions	12
4.3.2 Geologic Cross Sections	14
5.0 Building Exterior Assessments.....	15
5.1 General.....	15
5.2 Limits of Assessment.....	15
5.3 Description of Structures.....	16
5.4 Assessment Criteria.....	16
5.5 Assessment Results.....	17
6.0 Infrastructure.....	21
6.1 Existing Infrastructure.....	21
6.1.1 General.....	21
6.1.2 Water Lines.....	21
6.1.3 Gas Lines.....	22
6.1.4 Sewer lines.....	22
6.2 Infrastructure Observations.....	22
6.2.1 Laterals.....	23
6.2.2 Sewers.....	24

<u>Section</u>	<u>Page</u>
7.0 Conclusions.....	27
7.1 US Army Corps of Engineers, Philadelphia District Map.....	27
7.2 Geotechnical Investigation.....	27
7.3 Building Exterior Assessments.....	30
7.4 Infrastructure.....	30
7.4.1 Laterals.....	31
7.4.2 Sewers.....	31
8.0 Recommendations	33
8.1 Topographical Change Map.....	33
8.2 Subsurface Investigation.....	33
8.3 Building Exterior Assessments.....	34
8.4 Infrastructure.....	35
9.0 Bibliography	36
10.0 Appendix.....	37
A USACE Topographical Change Maps	
B Geotechnical Investigation	
C Building Exterior Assessment	
D Sewer/Lateral Investigation	
E Southeastern Pennsylvania Environmental Assistance Program, Section 566 of the Water Resources Development Act (WRDA) of 1996	