


APPENDIX L


Water Quality Data Figures & Isopleths (Quarters1-6)



CABRERA SERVICES
 RADIOLOGICAL • ENVIRONMENTAL • REMEDIATION
WWW.CABRERASERVICES.COM

Quarterly Monitoring Event, May 2007 [Q7]
 DuPont Chambers Works, Deepwater, NJ


Figure H-3
 Ra-226 + Ra-228 Contour Map - "A" and "B" Aquifers
 AOC 4




CABRERA SERVICES
 RADIOLOGICAL • ENVIRONMENTAL • REMEDIATION
WWW.CABRERASERVICES.COM

Quarterly Monitoring Event, May 2007 [Q7]
 DuPont Chambers Works, Deepwater, NJ

Figure H-4
 Thorium-230 Contour Map - "A" and "B" Aquifers
 AOC 4



0.019U "B" Aquifer
 "U" = undetected



0.019U "B" Aquifer
 "U" = undetected



CABRERA SERVICES
 RADIOLOGICAL • ENVIRONMENTAL • REMEDIATION
WWW.CABRERASERVICES.COM

Quarterly Monitoring Event, May 2007 [Q7]
 DuPont Chambers Works, Deepwater, NJ

Figure H-7
 Thorium-230 Concentrations - "B" Aquifer
 AOC 6